

OPERATOR'S MANUAL

MODEL: TG-03

COATING THICKNESS GAUGE



INTRODUCTION

The instrument is a ferrous coating thickness gauge designed for simply one hand operation.

- The Product features:
- LED backlight
 - LCD display reverse
 - Auto power off
 - Low-battery indicator
 - Calibration for normal use
 - Data logging function
 - Warning beeper triggers by hi/lo limit settings
 - Inch and Metric measurement options
 - Zeroing Plate and Standard Coating Plate
 - Attached with carrying strap
 - Soft carrying case

SAFETY INFORMATION


It is recommended that you read the safety and operation instructions before using the coating thickness gauge.

CAUTION

- Do not use the unit near any device which generates strong electromagnetic radiation or near a static electrical charge, as these may cause errors.
- Do not use the unit where it may be exposed to corrosive or explosive gases. The unit may be damaged, or explosion may occur.



- Do not keep or use this unit in an environment where it will be directly illuminated by sunshine, or where it condensation. If you do, it may be deformed, its insulation may be damaged, or it may no longer function according to specification.
- Do not place the meter on or around hot objects (70°C/158°F). It may cause damage to the case.
- If the meter is exposed to significant changes in ambient temperature, allow 30 minutes for temperature stabilization, before taking measurement.
- Condensation may form on the sensor when going from a cold to hot environment. Wait for 10 minutes for condensation to dissipate before taking measurements.
- This unit is not constructed to be waterproof and dustproof. Do not use it in a wet or very dusty environment.
- In order to take accurate measurement, make sure the sensing tip contacts the coated surface tightly without tilting.
- Please make sure there is no air bubbles between substrate and coating.
- **Substrate zeroing calibration must be implemented for each use.**
- **Two point calibration is suggested to implement for frequent testing points to increase measuring accuracy.**



WARNING



ELECTROMAGNETIC FIELD INTERFERENCE

This instrument uses magnetic field method to measure the coating thickness on ferrous metal base. If this meter was placed in the environment with 20mG (mini Gauss) or above, the accuracy would be affected. Suggest that the meter should to put far away from the interfered source at least 30cm.

Electromagnetic field strength:(※unit = mini Gauss)

Electromagnetic Source	0cm	30cm
Cellular Phone Charger	50 ~ 500	< 1
Notebook Power Supply	100 ~ 1000	< 5
LCD Display	10 ~ 100	< 1
Fan	100 ~ 1000	< 5
Reading Lamp	400 ~ 4000	< 10

※Any product with coil inside should be considered.



SPECIFICATION

ELECTRICAL

Detectable Substrate Material: Ferrous metal (iron, steel)

Thickness Range: 0 to 80.0mils (0 to 2000μm)

Display Resolution: 0.1mils/1μm

Accuracy:

- ±4dgts on 0 to 7.8mils
- ±(3% + 4dgts) on 7.9mils to 39.0mils
- ±(5% + 4dgts) on 39.1mils to 80.0mils
- ±10dgts on 0 to 199μm
- ±(3% + 10dgts) on 200μm to 1000μm
- ±(5% + 10dgts) on 1001μm to 2000μm

Response Time: 1 second.

GENERAL

Operating Environment: 32°F to 122°F (0°C to 50°C) at < 75% R.H.

Storage Temperature: -4°F to 140°F (-20°C to 60°C), 0 to 80% R.H. with battery removed from meter.

Accuracy: Stated accuracy at 18°C to 28°C(64°F to 82°F), <75% R.H.

Temperature Coefficient: 0.1x (specified accuracy) / °C (< 18°C or > 28°C)

Auto Power Off: 30 seconds.

Standby Consuming Current: < 6μA.

Battery: 1.5V (AAA size) x 2pcs.

Battery Life: 32 hours continuity use typical alkaline.

Low Battery Indication: The "⚡" is displayed when the battery voltage drops below the operating level.


Dimensions: 105mm (H) x 55mm(W) x 27mm(D).

Weight: Approx. 80g (including battery).


Product Use

DEFINITION

Zeroing Plate




Standard Coating Plate




Peel off the both side of protection film before use

※Peel off the protection films from foil before first use.

The product



Buttons



Button	Function
	Press the button to enter MENU/ selecting.
	Press the button to reverse the display. Press the button for 2 seconds to turn on or off backlight.
	Jumped off and return to the previous mode.
	Up/down adjusting. (select function, value)
	Press the button to substrate Zeroing Calibration. Press the button for 2 seconds to clear Calibrating Point.


※ During measure mode:

The three buttons are disabled.

※ During setting mode:

The two buttons are disabled.

The Display



No.	Symbol	Meaning
1	Fe	Ferrous
2	MAX	Maximum reading
	MIN	Minimum reading
	MAX - MIN	(Maximum - Minimum) reading
	AVG	Average reading
	n	Number of the reading
3		Low battery
4		Alarm indicator
5	MEM	Record is activated
6	CAL	Calibration is activated
7	μm, mils	Measurement units

Auto Power Off (APO):

Leave the gauge without operation for 30 seconds, power turns off automatically.

※During set mode, Auto Power Off function will be inactivated.

Measuring

- Gage automatically powers up and Measuring when probe is pressed.
- Put the probe to contact coated surface tightly, wait for the reading to appear and measurement is completed.(One sound “Beep” announced)
- If the coating thickness is out of range, the meter shows “----”.
- When the alarm is activated, measured exceed “Hi Limits” or “Lo Limits”, LCD display (updated) the measured value will be lit up along with pressing ▲ or ▼ symbol, the beeper emits a continuous or pulsed tone, warm users exceeds the Hi or Lo Limits value


CAUTION: Keep the sensing tip of the meter away from any substrate or any magnetic field.

MENU

In measuring mode, press button to enter menus,

CAL will blink.

With ▼ and ▲ button to select the function, browse the menus:




CAL Two point calibration


※During two point calibration, the foil and standard coating plate 1006μm can be replaced by uncoated substrate and a standard coating plate with known-thickness.

※When it is calibrated by user, its max calibrated value is 1100μm (43.3 mils).


In this mode, press button to enter two point calibration.




Into “low” value adjustments of the two point calibration, press ▲ or ▼ button to adjust reading, when it displays the desired value, press button to confirm.



Press the tip of the Gauge to contact coated surface tightly (Zeroing plate or uncoated substrate), Wait for one “Beep” sound announces.



Into “Hi” value adjustments of the two point calibration, press ▲ or ▼ to adjust reading, when it display the desired value, press button to confirm.




Press the tip of the Gauge to contact coated surface tightly (standard coating plate 1006μm or standard coating plate), wait for one “Beep” sound announces, exit two point calibration and return to measuring mode.

Before users finish two point calibration, if press button to exit two point calibration, since the calibration is not finished, it will not record its previous calibrated value.


rEE Record setting/ recall

The product can record 255 samples.


Stop recording after the 255th measured value.




In this mode, press button to enter recording setting.




Press ▲ or ▼ button to select the record on or off.




After it's selected, press button to confirm.



a. Recalling previous records:
To exit this mode, press button.
Press ▼ or ▲ button to browse previous records, its sequence as follows:





b. To delete all recorded data:


Press **DEL** button for five seconds.

Press **▼** or **▲** button to select the delete **00** or **YES**.


00, press **MENU** button to return to browse previous records.

YES, press **MENU** button to delete record and return to the measuring mode.


ALr Alarm setting



In this mode, press **MENU** button to enter the “Hi Limits” alarm setting mode.



Press **▲** or **▼** button to turn on or off the “Hi Limits” alarm.




After it's selected, press **MENU** button to enter the “Hi Limits value” alarm setting mode.



Press **▲** or **▼** button to adjust reading. When it displays the desired value, press **MENU** button to confirm the “Hi Limits” alarm, and enter the “Lo Limits” alarm mode setting.




Press **▲** or **▼** button to turn on or off the “Lo Limits” alarm. After it's selected, press **MENU** button to enter the “Lo Limits value” setting.




Press **▲** and **▼** to adjust reading. to meet the desired value, press **MENU** button to confirm the “Hi Limits” alarm, and return to measuring mode.

Alarm setting: Maximum is 2000μm(78.8 mils), Minimum is 0μm(0.0 mils).

Unit selecting



In this mode, press **MENU** button to enter to unit selecting.




Press **▲** or **▼** button to select the um or mils.



After it's selected, press **MENU** button to exit the unit selecting and return to measuring mode.


Calibrating Point Clearance:



In measuring mode, press **ZERO** button over 2 seconds to clear Calibrating Point. LCD will display “0000”. When calibration is not operated properly, the clearance function helps users to start it again.

MAINTENANCE

Installing and Replacing Battery



1. Power is supplied by 2pcs 1.5V (AAA SIZE).
2. The “ ” appears in the display when battery replacement is needed.
3. Remove the battery cover by gently sliding it onwards the bottom of the meter.
4. Remove the batteries from battery compartment.
5. Replace with 2 new AAA batteries with polarity as indicated on the bottom of Battery Compartment.
6. Replace the Battery Cover.

CAUTION: When not in use for long periods remove battery. Do not store in locations with high temperatures, or high humidity.

Cleaning

Periodically wipe the case with a damp cloth and detergent, do not use abrasives or solvents.