
СІТОСИТ ЗОК


Plasma Cutting - Anywhere, Anytime

The Citocut 30K plasma cutting system arrives ready to go for fast and precise cutting. With the 30K, forget the grinder – simply pick up the torch and cut in seconds.

Features

- Ultimate Portability Internal air compressor enables operation in environments where external compressed air is not available.
- Continuous Output Control Focus the arc for different material thickness.
- **Touch Start system** Reliable plasma arc initiation without high frequency.
- Rapid Arc Restrike Fast cutting through gaps, even expanded metal.
- Front Panel Purge Control Makes it easy to set the air flow rate without initiating the plasma arc.
- Cool Operation, Long Consumable Life New electrode and nozzle design save you money in the long run.
- Added Safety Our Parts-in-Place system detects correct installation of consumables and torch.
- Engine Drive Compatible Select a Lincoln Electric Vantage[®] to power your Citocut in remote locations.







Citocut 30K (W100000319) includes:

- Internal air compressor (external air connection also standard)
- Lincoln Electric LC30 Torch with 4 m cable
- Air regulator and pressure gauge
- Internal water separator
- Work clamp and cable
- Spare consumables
- Input power cord

Applications

- On site maintenance
- Small construction sites.
- Air ducting installation (HVAC)
- Demolition work
- Rental



INTERNAL

COMPRESSOR

OR EXTERNAL AIR



RECOMMENDED ACCESSORIES



Plasma Circle Cutting Guide Kit For cutting circles from 77-838 mm (3-33 in.) in diameter. Works with all Lincoln LC series plasma torches. Order W0300699A



Lincoln Electric I C30 Replacement Torch Includes 4 m (10 ft.) torch cable and one set of all required torch expendable parts Order W10000325



Two-wheeled undercarriage For stick and TIG inverters Order W0200002

REPLACEMENT TORCH CONSUMABLES

Consumable Wear

- It is normal for the electrode and nozzle to wear during operation.
- Electrodes should typically be replaced when erosion reaches 0.65 mm (0.025 in.).
- A green and erratic arc will indicate end of electrode life. The electrode should be immediately replaced.
- It is recommended that the Electrode and Nozzle be replaced as a complete set.

Lincoln Electric LC30 Parts

| Product Number | Description | | |
|----------------|---------------|--|--|
| W03X0893-75A | Electrode | | |
| W10000326 | Tip 0.8 mm | | |
| W03X0893-77A | Retaining Cap | | |
| W03X0893-5R | Swirl Ring | | |
| W03X0893-78R | Spacer | | |
| WU3XU893-78K | Spac | | |
| | | | |

CITOCUT 30K TORCH CONSUMABLES





Tip 0.8 mm

W10000326

W10000361



| | | Part | Quantity | Reference |
|-----------|--------|----------------|----------|--------------|
| Electrode | | | 10 | W03X0893-75A |
| | Gas | distributor | 3 | W03X0893-5R |
| | Tip | shielded - 30A | 10 | W100000326 |
| | Ret | aining Cap | 1 | W03X0893-77A |
| | Spacer | 40 - 80A | 3 | W03X0893-78R |

Type of cutting





Convenient for the operator, simply drag the nozzle on the plate. Well protected nozzle.

Electrode

W03X0893-75A



Gas

distributor

W03X0893-5R




Maximum flexibility and visibility of the plasma stream.

Retaining Cap

W03X0893-77A

Spacer

W03X0893-78R



| Product Name | Product Number | Input Power | Rated Output Current/Voltage/ Duty Cycle | Fuse (delayed) or Circuit Breaker | Pilot Current | Output Range | Air Pressure Required | Air Flow Rate Required | Dimensions H x W x D (mm) | Net Weight Without Torch (kg) |
|-----------------|-------------------|----------------|------------------------------------------------|--------------------------------------|------------------|-----------------|--------------------------|---------------------------|---------------------------------|-------------------------------------|
| CITOCUT 30K | W100000319 | 230/1/50 | 30A@60% 25A@100% | 16A | 20A | 15-30A | 5.0bar – 6,0bar | 125 ±10% l/min | 385 x 215 x 480 | 18,5 |

CUSTOMER ASSISTANCE POLICY

SPECIFICATIONS

The business of The Lincoln Electric Company® is manufacturing and selling high quality welding equipment, consumables, and cutting equipment. Our challenge is to meet the needs of our customers and to exceed their expectations. On occasion, purchasers may ask Lincoln Electric for information or advice about their use of our products. Our employees respond to inquiries to the best of their ability based on information provided to them by the customers and the knowledge they may have concerning the application. Our employees, however, are not in a position to verify the information provided or to evaluate the engineering requirements for the particular weldment. Accordingly, Lincoln Electric does not warrant or guarantee or assume any liability with respect to such information or advice. Moreover, the provision of such information or advice does not create, expand, or alter any warranty on our products. Any express or implied warranty that might arise from the information or advice, including any implied warranty of merchantability or any warranty of fitness for any customers' particular purpose is specifically disclaimed.

Lincoln Electric is a responsive manufacturer, but the selection and use of specific products sold by Lincoln Electric is solely within the control of, and remains the sole responsibility of the customer. Many variables beyond the control of Lincoln Electric affect the results obtained in applying these types of fabrication methods and service requirements.

Subject to Change - This information is accurate to the best of our knowledge at the time of printing. Please refer to www.lincolnelectric.eu for any updated information.

